

Install Instruction



Name	Date modified	Type	Size
Mach Screens	3/11/2019 10:05 AM	File folder	
5-axis CNC	3/11/2019 2:06 PM	XML Document	113 KB
5axis Testing code.tap	1/16/2017 1:08 PM	TAP File	49 KB
Mach3setup	2/28/2013 11:00 AM	WPS PDF 文档	510 KB
Mach3Tutorial	2/28/2013 11:01 AM	WPS PDF 文档	2,769 KB
Mach3Version3.043.066	2/10/2014 5:28 PM	Application	26,341 KB
Read Me First!	7/25/2019 9:53 AM	Text Document	1 KB
UC100 USB adapter plugin installation	2/3/2017 3:06 PM	Compressed (zipp...	40,265 KB

1. Download Mach3 (There is Installation in CD)
2. Download Mach plugin for your Cable
 - If you are using UC100, Click 'UC100 usb adapter plugin installation' to download
3. Copy "5-axis CNC.xml" to Mach3 folder
4. Setup Mach3 5-Axis Screen
 - A. Go to C D - Mach Screen - Mach3 , And copy the UT Buttons-JPG folder to Mach3 Folder - Bitmaps - MillBitmaps
 - B. Copy 6Axis.set directly to Mach3 folder

IF YOU ALREADY HAVE PURCHASED A LICENSE:

Download the license file(Mach1Lic.dat) to Mach3 Folder
Then restart the software

