



6 axis Breakout board. Built in O-class Optical-coupler for any CNC stepper Motor driver

- 1: DB25 male connector.
- 2: Output Pin: P1, P2, P3, P4, P5, P6, P7, P8, P9, P14, P16, P17.
- 3: Input Pin: P10, P11, P12, P13, P15.
- 4: GND Pin: P18-P25