



- 6 axis Breakout board, Built in C-class Optical-coupler for any CNC stepper Motor driver**
- 1: DB25 male connector.
 - 2: Output Pin: P1, P2, P3, P4, P5, P6, P7, P8, P9, P14, P16, P17.
 - 3: Input Pin: P10, P11, P12, P13, P15.
 - 4: GND Pin: P18-P25.