

KL-DB25 Wiring Diagram

Axis	Step	Direction
X	2	3
Y	4	5
Z	6	7
A	8	9
B	14	15
C	16	17

Axis	Pin
Estop	10
X	11
Y	12
Z	13
Tool Touch Plate	15

