







DRAWING:
PM-30 X Axis 2005 DUF Ball Screw



DRAWING:
PM-30 Y Axis 2005 DUF Ball Screw



DRAWING:
PM-30 Z Axis 2005 DUF Ball Screw